


# QUICK START

Cleaning Plates\*  
PSPiX<sup>2</sup>


\* Plaques nettoyantes  
Placas de autolimpeza  
Lastrine di pulizia  
Reinigungsfolien  
Reinigingsplaatjes  
清洗片  
クリーニングプレート  
Очищающие пластины



1




2



3



4





Loss of efficiency  
Perte d'efficacité  
Effizienzverlust  
Efficiëntieverlies  
Pèrdua de eficiència  
Perdita di efficienza  
效率的损失  
効率損失  
потеря эффективности

Non contractual document – Ref 011706 C - November 2021 - Copyright © 2021 SOPRO. All rights reserved. No information or part of this document may be reproduced or transmitted in any form without the prior permission of SOPRO



MANUFACTURER/FABRICANT  
**SOPRO** - A company of ACTEON Group  
ZAC Athélia IV - 13705 LA CIOTAT Cedex - France  
Tel. +33 (0) 442 980 101 - Fax + 33 (0) 442 717 690